

Bend Stiffener



ext. sh. following / during jetting



Buoyancy clamp



Buoyancy Module (Foinaven type)



External sheath condition under repair clamps / tether clamps and adjacent to rigging



Beneath Uraduct




Riser End Termination




DMAC



Riser external sheath condition following water jetting



'2008' type inner buoyancy clamp



2008 buoyancy module

